

# Lead Work Site Entrance and Exit Procedures

## Entrance

1. All entrance and exits to the containment area shall be through the decontamination room or changing area.
2. All personnel entering the containment area must first sign the "Hazardous Work Area Sign in Log" noting times of entrance and exit.
3. Personnel should change from street clothes to work clothes.
4. No personnel shall enter the containment area without proper protective equipment.
5. Proper protective gear shall include but is not limited to, protective clothing such as tyvek suits, respiratory gear appropriate to the expected exposure level, shoe covers, safety glasses, gloves, hard hats, etc.
6. Respiratory equipment shall be inspected for defects, put on, and fit checked before entering.
7. Food, drinks, gum, and tobacco products are not allowed in the containment area.

## Exit

1. Before entering the changing area, all personnel shall remove as much visible contamination as possible.
2. Upon entrance to the changing area, personal protective clothing and shall be removed and placed in a proper container.
3. Any surface dust on clothing should be vacuumed off.
4. Respiratory equipment should be wet wiped to remove excess contamination.
5. Respiratory equipment shall be stored in a proper container.
6. Thoroughly wash hands, face, forearms, and any other exposed skin surfaces or shower if available on site.
7. Change into street clothes.
8. All personnel shall note exit time in the "Hazardous Work Area Sign in Log".

**Failure to follow the above entrance and exit procedures may cause the spread of lead contamination and may cause potential exposure to lead in workers and their families.**